



**\*\*PLEASE NOTE\*\*** Data points as mapped correspond to field data while road and stream layers were obtained through the Land and Resource Data Warehouse. Field data points do not always match up exactly with mapped streams and roads. Duplicate road layers in the maps created by Marlim are due to using both FTEN and DRA road layers, in order to map the complete road network. Some overlap is present between the layers.

### Legend

#### Crossing Status by Year

2012	2013	2014
■ Barrier	▲ Barrier	● Barrier
■ Priority	▲ Priority	★ Priority
■ Passable	▲ Passable	● Passable
■ Potential	▲ Potential	● Potential
■ Unknown	▲ Unknown	● Unknown
■ DNE	▲ DNE	● DNE
		× No Assessment Required*
		● Access Data

#### Roads

- Unassessed
- Inaccessible
- Assessed 2012
- Assessed 2013
- Assessed 2014

#### Contours

- 20m Interval

#### Fish Habitat

- None
- Inferred
- Observed
- Lakes

#### Watersheds

- Boundary
- 5005 Label

1:10,000

\*Sites that are either: inaccessible due to overgrown roads or denied permission from landowner, or have no downstream channel.

	Fish Passage Culvert Investigations - Babine TSA		Date: February 2015	Map Title: M14-249
	Contract: EN15TAH414			
	MarLim Ecological Consulting Ltd.		Project: 327.14.01	Page: 8
	Phone/Fax: 604-531-4338 Web: <a href="http://www.marlimecological.com">www.marlimecological.com</a> Email: <a href="mailto:mail@marlimecological.com">mail@marlimecological.com</a>			