

**\*\*PLEASE NOTE\*\*** Data points as mapped correspond to field data while road and stream layers were obtained through the Land and Resource Data Warehouse. Field data points do not always match up exactly with mapped streams and roads. Duplicate road layers in the maps created by Marlim are due to using both FTEN and DRA road layers, in order to map the complete road network. Some overlap is present between the layers.

**Legend**

**Crossing Status by Year**

- | 2012        | 2013           |
|-------------|----------------|
| ▲ Barrier   | ● Barrier      |
| ▲ Priority  | ★ Priority     |
| ▲ Passable  | ● Passable     |
| ▲ Potential | ● Potential    |
| ▲ Unknown   | ● Unknown      |
| ▲ DNE       | ● DNE          |
|             | × Not Assessed |
|             | ● Access Data  |

**Roads**


- Unassessed
- Inaccessible
- Assessed 2012
- Assessed 2013

**Contours**

- 20m Interval

**Fish Habitat**

- None
- Inferred
- Observed



1:10,000



Fish Passage Culvert Investigations - Babine TSA

Contract: EN13TLA010

Date:  
January 2014

Map Title:  
M13-258

**MarLim Ecological Consulting Ltd.**

Phone/Fax: 604-531-4338 Web: www.marlimecological.com Email: mail@marlimecological.com

Project:  
327.13.01

Page:  
4