


<p>Legend</p> <p>Crossing Status by Year</p> <p>2012 2013 2014 2015</p> <p> ■ Barrier ■ Potential ▲ Barrier ▲ Potential ● Barrier ● Potential ○ Barrier ○ Potential ■ Priority ■ Unknown ▲ Priority ▲ Unknown ● Priority ● Unknown ○ Priority ○ Unknown ■ Passable ■ DNE ▲ Passable ▲ DNE ● Passable ● DNE ○ Passable ○ DNE </p> <p>All Years: ● Access Data x No Assessment Required*</p>										<p>Roads</p> <p> — Unassessed — Inaccessible — Assessed 2012 — Assessed 2013 — Assessed 2014 — Assessed 2015 </p> <p>Fish Habitat</p> <p> — None — Inferred — Observed </p> <p>Contours</p> <p> — 20m Interval </p> <p>Watersheds</p> <p> — Boundary — 5005 Label </p> <p>Lakes</p> <p>□ Lakes</p>										<p>**PLEASE NOTE** Data points as mapped correspond to field data while road and stream layers were obtained through the Land and Resource Data Warehouse. Field data points do not always match up exactly with mapped streams and roads.</p> <p>Duplicate road layers in the maps created by MarLim are due to using both FTEN and DRA road layers, in order to map the complete road network. Some overlap is present between the layers.</p> <p>*Sites that are either: inaccessible due to overgrown roads or denied permission from landowner, or have no downstream channel.</p>										 <p>MARLIM ECOLOGICAL CONSULTING LTD.</p>										<p>Fish Passage Culvert Investigations - Babine TSA</p> <p>Contract: EN15TAH414</p>										<p>Date: November 2015</p> <p>Map Title: Overview Tile A</p>										<p>MarLim Ecological Consulting Ltd.</p> <p>Phone/Fax: 604-531-4338 Web: www.marlimecological.com Email: mail@marlimecological.com</p>										<p>Project: 327.15.01</p> <p>Page: 2</p>									
---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--