



**Legend**

**Crossing Status by Year**

**2012**

**2013**

**2014**

**2015**

Barrier

Potential

Unknown

Passable

Barrier

Potential

Unknown

Passable

Barrier

Potential

Unknown

Passable

Barrier

Potential

Unknown

Passable

**All Years:**

Access Data

No Assessment Required\*

**Roads**

Unassessed

Inaccessible

Assessed 2012

Assessed 2013

Assessed 2014

Assessed 2015

**Fish Habitat**

None

Inferred

Observed

Lakes

**Contours**

20m Interval

**Watersheds**

Boundary

5005 Label

0 375 750 1,500 2,250 3,000

Meters

1:50,000

**\*\*\*PLEASE NOTE\*\*\*** Data points as mapped correspond to field data while road and stream layers were obtained through the Land and Resource Data Warehouse. Field data points do not always match up exactly with mapped streams and roads. Duplicate road layers in the maps created by Marlim are due to using both FTEN and DRA road layers, in order to map the complete road network. Some overlap is present between the layers.

\*Sites that are either: inaccessible due to overgrown roads or denied permission from landowner, or have no downstream channel.

**Fish Passage Culvert Investigations - Babine TSA**

Contract: EN15TAH414

**MarLim Ecological Consulting Ltd.**

Phone/Fax: 604-531-4338 Web: www.marlimecological.com Email: mail@marlimecological.com

Date: November 2015

Project: 327.15.01

Map Title: Overview Tile F

Page: 7